

MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 12/5/24

Requested by Somy Mathew

Department 6B ward Location 6th floor.

SR. No.	Machine	Model	Complaint
D770B140005	DVT machine	DVT 7700	Not working.

Check within Week

ASAP

Engineer Comments

End Comments



Requested by

Checked By

Approved by

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



شركة أتكو التكنولوجية

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجهراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 60267

Customer Alor Hospital	Equipment compressible limb therapy system		
	Model No. DRT-7700		
	Serial No. D-770B14 040005		
Authorized Person	Manufacturer Wanjin		
Customer Complaint	Location		
	Contract / Order No.		
Services / Check Carried out ☐ Inspection / Cleaning ☐ Calibration / Performance ☐ Interface / Communication ☐ Safety Checks ☐ Electrical / Electronics ☐ Accessories Check ☐ Optics Checks ☐ Pneumatic Checks ☐ Hydraulic Checks ☐ Operational Error ☐ Mechanical Checks ☐ _____	☐ Installation ☐ Warranty ☒ Repair ☐ On Charge ☐ Maintenance ☐ Contract ☐ Upgrade ☐ _____		
	Time Spent		
Remarks Service call attendance we inspect the unit and found that the limb therapy can cut connector is not damaged. we replaced the connector cable with another spare one. checked and confirmed that the unit is working properly.			
No.	Spare Parts Used	Part No.	Qty.
Service Engineer N. D. M. ATCO Technology Co. Signature Date 25/05/2022	Authorized Person Signature Date 31/5/2022	Customer / User Signature Date	