



MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 04/3/2024

Requested by Dr. Asem Kamel

Department Dental Location 6th floor

SR. No.	Machine	Model	Complaint
72210006	Water lase air compression Tubings	Biolase Lase [water lase ysgg]	Tubings are not working

Check within ☐ Week

☒ ASAP

Engineer Comments

Connection of tube was removed

End Comments

unit is working properly

د. عاصم محمد كامل
مستشفى العرف
Requested by

Checked By

Approved by

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO. 336218



شركة أتكو التكنولوجيه

تلفون: ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس: ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب: ٢٣٥٥ الجهراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 58929

Customer Alor Hospital	Equipment Dental water lase compressed Air		
	Model No.		
	Serial No.		
Authorized Person	Manufacturer		
Customer Complaint	Location Dental clinic (Dr. Asim)		
	Contract / Order No.		
Services / Check Carried out ☐ Inspection / Cleaning ☐ Calibration / Performance ☐ Interface / Communication ☐ Safety Checks ☐ Electrical / Electronics ☐ Accessories Check ☐ Optics Checks ☐ Pneumatic Checks ☐ Hydraulic Checks ☐ Operational Error ☐ Mechanical Checks ☐	☐ Installation ☐ Warranty ☒ Repair ☐ On Charge ☐ Maintenance ☐ Contract ☐ Upgrade ☐		
	Time Spent		
Remarks Service call attended. we inspect the unit and found that the compressed air connection is removed from the chair we replace the compressed air connection using the connector and reducers. checked and confirmed that the compressed air connection is working properly			
No.	Spare Parts Used	Part No.	Qty.
Service Engineer ATCO Technology Co. Signature Date 07/03/2024		Authorized Person Signature Date	
Customer / User Signature د. عاصم محمد كامل Date 11-3-2024		مستشفى علاج الأسنان د. عاصم محمد كامل	