

قسم الصيانة
SERVICE REPORT

7774

Customer : Alort Hospital

Date : 17/07/2024

Department : Radiology

Type of equipment : Dms BMD

Model No. : Dexa Stratos

Serial No. : _____

Service Call Type :

Installation

Repair

Maintenance

Emergency

☐☐☐☐

Warranty

Contract

Chargeable

Others

☐☐☐☒

ENGINEER'S REPORT :

Fault : Unit Inspection

Action : Operation has been checked.

Physical Inspection, Aging Test

Done. Log file has been taken for analysis.

Remarks : Will send to Manufacturer and

Warranty : update you ASAP.

Repair Time : _____

K.D.

Fils

Parts Used : _____

Invoice No. : _____ Date : _____

M. J. J.

ENGINEER'S NAME AND SIGNATURE

Alort Hospital
ALORT HOSPITAL
17/7/2024

CUSTOMER'S NAME AND SIGNATURE