

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



شركة أتكوتكنولوجيه

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجهراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 60493

Customer	Alto & Hospital Jahra	Equipment	Suction Unit
		Model No.	Dominant Flex
		Serial No.	1596853, 1596854
Authorized Person		Manufacturer	Medela
Customer Complaint	low suction	Location	OR
		Contract / Order No.	

Services / Check Carried out

- | | |
|--|--|
| ☐ Inspection / Cleaning | ☐ Optics Checks |
| ☐ Calibration / Performance | ☐ Pneumatic Checks |
| ☐ Interface / Communication | ☐ Hydraulic Checks |
| ☐ Safety Checks | ☐ Operational Error |
| ☐ Electrical / Electronics | ☐ Mechanical Checks |
| ☐ Accessories Check | ☐ |

- | | |
|--|---|
| ☐ Installation | ☐ Warranty |
| ☒ Repair | ☒ On Charge |
| ☐ Maintenance | ☐ Contract |
| ☐ Upgrade | ☐ |

Time Spent

Remarks

Found the vacuum bottle inside the unit filled with dust particles. Cleaned the bottle. Checked and found it working properly.

No.	Spare Parts Used	Part No.	Qty.
	affected for cleaned inside.		

Service Engineer Sujith ATCO Technology Co. Signature Date 18/5/24	Authorized Person Signature Date 18/5/24	Customer / User Signature Date
--	--	--------------------------------------