



SERVICE / INSTALLATION REPORT

No.: 63756

Customer	ALORF HOSPITAL	Equipment	Washer & Disinfecton
	Jahra	Model No.	Uniclear
		Serial No.	230506 #2
Authorized Person		Manufacturer	MMM
Customer Complaint		Location	CSSD
Unloading door not open		Contract / Order No.	

Services / Check Carried out ☒ Inspection / Cleaning ☒ Calibration / Performance ☒ Interface / Communication ☒ Safety Checks ☒ Electrical / Electronics ☒ Accessories Check ☐ Optics Checks ☐ Pneumatic Checks ☐ Hydraulic Checks ☐ Operational Error ☐ Mechanical Checks ☐	☐ Installation ☐ Warranty ☐ Repair ☐ On Charge ☐ Maintenance ☐ Contract ☐ Upgrade ☒ <u>FM</u>
Time Spent	

Remarks

Found Unloading door not opened.
 Reset the unloading door relay and solved the issue.
 Run the complete cycle and confirmed the unit is working perfectly.
 Reset the unloading door relay due to technical issue.

No.	Spare Parts Used	Part No.	Qty.
-	ATTEN RESET MACHINE WORKING. ON 23/6/25		
	RESET AGAIN done.		
	MACHINE WORKING		

Service Engineer ATCO service team ATCO Technology Co. Signature Date 9/06/2025	Authorized Person 28/6/25 Signature Date	Customer / User Signature Date
---	--	---