

MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 29/4/25

Requested by Amr Elshaykh

Department O.R Location Equipment Room

SR. No.	Machine	Model	Complaint
1151798	warmer cabinet		Display not working

Check within

☐ Week

☐ ASAP

Engineer Comments

End Comments

Amr Elshaykh
Requested by

Checked By

Approved by

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO. 336218



شركة أتكو التكنولوجية

تلفون: ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس: ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب: ٢٣٥٥ الجاهراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 63729

Customer	Alorj Hospital	Equipment	Warner cabinet
		Model No.	FWR/SP
		Serial No.	1131798
Authorized Person		Manufacturer	Hogami
Customer Complaint		Location	OR
		Contract / Order No.	
Services / Check Carried out		☐ Installation	☐ Warranty
		☒ Repair	☐ On Charge
		☐ Maintenance	☐ Contract
		☐ Upgrade	☐ _____
		Time Spent	
☐ Inspection / Cleaning		☐ Optics Checks	
☐ Calibration / Performance		☐ Pneumatic Checks	
☐ Interface / Communication		☐ Hydraulic Checks	
☐ Safety Checks		☐ Operational Error	
☐ Electrical / Electronics		☐ Mechanical Checks	
☐ Accessories Check		☐ _____	

Remarks

Service call attended.
we inspect the unit and found that the display is not working.
Need to check the battery on the display failure. we will bring new battery and test the unit later

No.	Spare Parts Used	Part No.	Qty.

Service Engineer

ATCO Technology Co.

Signature

Date

Authorized Person

Signature

Date

Customer / User

Signature

Date