

Central Circle



MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 9 / 11 / 23.

Requested by Dinar Maulida,

Department Urology Location 2A Surgery, 2nd Floor

SR. No.	Machine	Model	Complaint
2202833	Uroflowmetry	Smart Flow	The cable was broke.

Check within Week

☒ ASAP

Engineer Comments

adaptor was broken, waiting for the quotation.

End Comments

Replaced new power supply "

Requested by _____

Checked By _____

Approved by _____



EXCELLENCE IN HEALTHCARE SINCE 1979

CENTRAL CIRCLE CO.

شركة الدائرة المركزية

P.O. Box 1015 Salmieh, 22011 Kuwait, Al-Shuhada Street, Sharq, Kuwait Al-Hamra Business Tower, 69th Floor,
Tel.: +965 1869 869 - Hotline: +965 9445 0011 Fax: +965 2205 8895 Email: ccc-service@centralcircleco.com www.centralcircleco.com

NO. 96042 SERVICE REPORT PAGE 1 /

CUSTOMER DATE

LOCATION

EQUIPMENT

MODEL

SERIAL NO. TAG NO. CC NO.

TYPE OF JOB

☐ REPAIR ☐ MODIFICATION ☐ MAINTENANCE
☐ CHARGEABLE ☐ WARRANTY ☐ CONTRACT NO.
☐ INSTALLATION ☐ ORDER NO. ☐ INVOICE NO.

COMPLAINT

ACTION

TOTAL HOURS WORK TRAVEL JOB COMPLETED ☐ YES ☐ NO

PARTS USED

ITEM	PART NO	DESCRIPTION	QTY

CUSTOMER NAME HOSP. ENGR. NAME CC ENGINEER NAME
SIGNATURE SIGNATURE SIGNATURE



EXCELLENCE IN HEALTHCARE SINCE 1979

CENTRAL CIRCLE CO.

شركة الدائرة المركزية

P.O. Box 1015 Salmieh, 22011 Kuwait, Al-Shuhada Street, Sharq, Kuwait Al-Hamra Business Tower, 69th Floor,
Tel.: +965 1869 869 - Hotline: +965 9445 0011 Fax: +965 2205 8895 Email: ccc-service@centralcircleco.com www.centralcircleco.com

NO. 96342 SERVICE REPORT PAGE 1 /

CUSTOMER AL KUT HOSPITAL DATE 15/12/2024

LOCATION Urology

EQUIPMENT - Albion smart flow
MODEL smart flow
SERIAL NO. 2202 833 TAG NO. CC NO.

TYPE OF JOB
☐ REPAIR ☐ MODIFICATION ☐ MAINTENANCE
☐ CHARGEABLE ☐ WARRANTY ☐ CONTRACT NO.
☐ INSTALLATION ☐ ORDER NO. SO ☐ INVOICE NO.

COMPLAINT

ACTION According to quotation 104768/2023
we delivered the item
(Power supply - smart flow)

TOTAL HOURS WORK TRAVEL JOB COMPLETED ☐ YES ☐ NO

PARTS USED

ITEM	PART NO	DESCRIPTION	QTY

CUSTOMER NAME Jemal Charko HOSP. ENGR. NAME Mohamed Askar
SIGNATURE SIGNATURE SIGNATURE



EXCELLENCE IN HEALTHCARE SINCE 1979

CENTRAL CIRCLE CO.

شركة الدائرة المركزية

P.O. Box 1015 Salmieh, 22011 Kuwait, Al-Shuhada Street, Sharq, Kuwait Al-Hamra Business Tower, 69th Floor,
Tel.: +965 1869 869 - Hotline: +965 9445 0011 Fax: +965 2205 8895 Email: ccc-service@centralcircleco.com www.centralcircleco.com

NO. 96342

SERVICE REPORT

PAGE 1 /

CUSTOMER DATE

LOCATION
.....
.....

EQUIPMENT

MODEL

SERIAL NO. 22-2-833 TAG NO. CC NO.

TYPE OF JOB

☐ REPAIR

☐ MODIFICATION

☐ MAINTENANCE

☐ CHARGEABLE

☐ WARRANTY

☐ CONTRACT NO.

☐ INSTALLATION

☐ ORDER NO. SO

☐ INVOICE NO.

COMPLAINT

ACTION

TOTAL HOURS

WORK

TRAVEL

JOB COMPLETED

☐ YES

☐ NO

PARTS USED

ITEM	PART NO	DESCRIPTION	QTY

CUSTOMER NAME

HOSP. ENGR. NAME

Mohamed Askar
CC ENGINEER NAME

SIGNATURE

SIGNATURE

SIGNATURE



EXCELLENCE IN HEALTHCARE SINCE 1979

CENTRAL CIRCLE CO.

شركة الدائرة المركزية

P.O. Box 1015 Salmieh, 22011 Kuwait, Al-Shuhada Street, Sharq, Kuwait Al-Hamra Business Tower, 69th Floor,
Tel.: +965 1869 869 - Hotline: +965 9445 0011 Fax: +965 2205 8895 Email: ccc-service@centralcircleco.com www.centralcircleco.com

NO. 96342 SERVICE REPORT PAGE 1 /

CUSTOMER DATE

LOCATION
.....
.....

EQUIPMENT

MODEL

SERIAL NO. TAG NO. CC NO.

TYPE OF JOB

- ☐ REPAIR ☐ MODIFICATION ☐ MAINTENANCE
☐ CHARGEABLE ☐ WARRANTY ☐ CONTRACT NO.
☐ INSTALLATION ☐ ORDER NO. SO ☐ INVOICE NO.

COMPLAINT

ACTION

.....
.....
.....
.....
.....
.....
.....
.....
.....
.....

TOTAL HOURS WORK TRAVEL JOB COMPLETED ☐ YES ☐ NO

PARTS USED

ITEM	PART NO	DESCRIPTION	QTY

CUSTOMER NAME HOSP. ENGR. NAME CC ENGINEER NAME Mohamed Askar

SIGNATURE SIGNATURE SIGNATURE