

MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 02/01/25

Requested by Prasanth

Department C.S.S.D Location CSSD Basement

SR. No.	Machine	Model	Complaint
<u>230506</u>	<u>washer</u>	<u>uniclean</u>	<u>unloading door</u>
	<u>disinfection</u>	<u>P2 TI</u>	<u>not opening</u>
			<u>washer</u>
			<u>washer</u>
			<u>water spray</u>
			<u>not working</u>

Check within

Week

ASAP

Engineer Comments

End Comments

Prasanth

Requested by

Checked By

Approved by

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO. 336218



شركة أتكو التكنولوجية

تلفون: (+965) 24743017 / 24567725

فاكس: (+965) 24743019 / 24567792

ص.ب: ٢٣٥٥ الجهر، ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 63793

Customer	Alor Hospital	Equipment	CSSD washer
		Model No.	chiclan PL 11
		Serial No.	230506
Authorized Person		Manufacturer	MMM
Customer Complaint		Location	CSSD
unloading door not open		Contract / Order No.	

Services / Check Carried out

- | | |
|---|---|
| ☐ Inspection / Cleaning | ☐ Optics Checks |
| ☐ Calibration / Performance | ☐ Pneumatic Checks |
| ☐ Interface / Communication | ☐ Hydraulic Checks |
| ☐ Safety Checks | ☐ Operational Error |
| ☐ Electrical / Electronics | ☐ Mechanical Checks |
| ☐ Accessories Check | ☐ _____ |

- | | |
|---|---------------------------------|
| ☐ Installation | ☐ Warranty |
| ☒ Repair | ☐ On Charge |
| ☐ Maintenance | ☐ Contract |
| ☐ Upgrade | ☐ _____ |

Time Spent

Remarks: Service call attended. we inspect the unit and found that the unloading door is not opening. we found that the Q10k relay is faulty, we replaced the relay and found that the unit is working properly.

No.	Spare Parts Used	Part No.	Qty.
	working now		

Service Engineer M. Alor ATCO Technology Co. Signature: Date: 05/11/2025	Authorized Person Signature: _____ Date: _____	Customer / User Signature: _____ Date: _____
--	--	--