



MEDICAL EQUIPMENT REPAIR REQUEST

No. # 3 Date: 13/01/2025

Requested by: Ferre Jory Williams

Department: NICU Location: 3rd Floor

SR. No.	Machine	Model	Complaint
5627/161006	Transpat Ventilator	Hamilton	* screen not responding to touch
			* Pressure on SIMV is too high

Check within Week ☒ ASAP

Engineer Comments

End Comments

Ferre

Requested by

Checked by

Approved by

شركة وربة للتجهيزات الطبية ذ.م.م

WARBA MEDICAL SUPPLIES CO. W.L.L.

تلفون المكتب : ٢٢٣٢٣٨٥٦ / ٢٢٣٢٣٨٥٧ - فاكس : ٢٢٣٢٣٨٦٤ - س.ت : ٢٧٤٦٨ - ص.ب : ٢٦٢٦٧ الصفاة ١٣١٢٣ الكويت
Al Kharafi Tower (Building 6) - 1st Floor, Hamad Al Sagr Street, Block 14, Qibla, Kuwait Tel. Off.: 22323856/57 Fax 22323864
C.R.: 27468 - P.O. Box: 26267 Safat, 13123 Kuwait, E-mail: med@warbamed.com, www.warbamed.com

FIELD SERVICE REPORT

Service Report No: A	11088	Date: 13/01/25	Quarter: ☐ I ☐ II ☐ III ☐ IV
Customer:	ALORF HOSPITAL	Equipment Location:	NIKU
Maintenance Contract No.:		Contract Serial No.:	
Equipment Name:	VENTILATOR		
Manufacturer:	Hamilton	Model :	T1
Serial Number:	5627		
Type of Job ☐ Preventive Maintenance ☐ Installation ☐ Warranty Replacement ☒ Emergency Maintenance ☐ Chargeable Repair ☐ Warranty Repair			
Maintenance Carried out and Final Status of the Instrument: - Replaced faulty FRONT PANEL checked all functions working okay			

Parts Used

No.:	Part Number:	Description	Quantity
1	10101031	Front Panel (SN 9729)	1

Remarks:

Name: Rishad	Name:	Authorized Signature & Stamp Biomedical Department
Warba Engineer Signature	End User Signature & Stamp	



شركة وربة للتجهيزات الطبية ذ.م.م.

WARBA MEDICAL SUPPLIES CO. W.L.L.

تلفون المكتب : ٢٢٣٢٣٨٥٦ / ٢٢٣٢٣٨٥٧ - فاكس : ٢٢٣٢٣٨١٤ - س.ت : ٢٧٤٦٨ - ص.ب : ٢٦٢٦٧ الصفاة ١٣١٢٣ الكويت
Al Kharafi Tower (Building 6) - 1st Floor, Hamad Al Sagr Street, Block 14, Qibla, Kuwait Tel. Off.: 22323856/57 Fax 22323864
C.R.: 27468 - P.O. Box: 26267 Safat, 13123 Kuwait, E-mail: med@warbamed.com, www.warbamed.com

FIELD SERVICE REPORT

Service Report No: A	11088	Date: 13/01/25	Quarter: ☐ I ☐ II ☐ III ☐ IV
Customer:	ALORF HOSPITAL	Equipment Location:	NIKU
Maintenance Contract No.:		Contract Serial No.:	
Equipment Name:	VENTILATOR		
Manufacturer:	Hamilton	Model :	T1
Serial Number:	5627		
Type of Job			
☐ Preventive Maintenance	☐ Installation	☐ Warranty Replacement	
☒ Emergency Maintenance	☐ Chargeable Repair	☐ Warranty Repair	
Maintenance Carried out and Final Status of the Instrument:			
- Replaced faulty FRONT PANEL			
- checked all functions working okay			

Parts Used

No.:	Part Number:	Description	Quantity
1	10101031	Front Panel (SN 9729).	1

Remarks:

Name: Rishad	Name: Rishad	Authorized Signature & Stamp Biomedical Department
Warba Engineer Signature	End User Signature & Stamp	