

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



log no - 1775

شركة أتكو التكنولوجية

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 60866

Customer	Alor Hospital Jahra	Equipment	Mammogram Unit								
		Model No.	Helix Plus C								
		Serial No.	HLBC/0063/C1								
Authorized Person		Manufacturer	Melaluma								
Customer Complaint		Location	X-Ray								
		Contract / Order No.									
Services / Check Carried out	<table><tr><td>☐ Installation</td><td>☐ Warranty</td></tr><tr><td>☐ Repair</td><td>☐ On Charge</td></tr><tr><td>☐ Maintenance</td><td>☐ Contract</td></tr><tr><td>☐ Upgrade</td><td>☐ _____</td></tr></table>			☐ Installation	☐ Warranty	☐ Repair	☐ On Charge	☐ Maintenance	☐ Contract	☐ Upgrade	☐ _____
☐ Installation	☐ Warranty										
☐ Repair	☐ On Charge										
☐ Maintenance	☐ Contract										
☐ Upgrade	☐ _____										
☐ Inspection / Cleaning	☐ Optics Checks	Time Spent									
☐ Calibration / Performance	☐ Pneumatic Checks										
☐ Interface / Communication	☐ Hydraulic Checks										
☐ Safety Checks	☐ Operational Error										
☐ Electrical / Electronics	☐ Mechanical Checks										
☐ Accessories Check	☐ _____										

Remarks

From manufacturer, they came
to check the log files
and signal status.
And will be updating asap

No.	Spare Parts Used	Part No.	Qty.

Service Engineer Signature Date	Authorized Person Signature Date	Customer / User Signature Date
---------------------------------------	--	--------------------------------------