

MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 28-05-24

Requested by DR. RAED

Department ENT Location 5th Flr - Alorif hospital

SR. No.	Machine	Model	Complaint
<u>EN2000597</u>	<u>AIDA C</u>	<u>WD 310</u>	<u>Loose cable; screen images are not shown clearly</u>

Check within Week

☒ ASAP

Engineer Comments

Display cable loose

End Comments

unit is working properly.


ERIM W. CHALLES

Requested by

Checked By

Approved by



DEPT: Sergical 23/ 50225

PROBLEM, DIAGNOSIS AND ACTION

- * The unit has been checked and found display cable loose.
- * The issue has been repaired

REMARKS

All functions are working fine.

JOB COMPLETED ☐ Yes ☐ No

AWAITING PARTS ☐ Yes ☐ No

ATC ENGINEER SIGNATURE

USER SIGNATURE

AUTHORIZED SIGNATURE & STAMP

22 Jan 18

K

www.atc.com.kw