



MEDICAL EQUIPMENT REPAIR REQUEST

No. # 10 Date: 16/01/25

Requested by: Ferre Jny Williams

Department: NICU Location: 3rd Floor

SR. No.	Machine	Model	Complaint
H0HT 50690	Medical Incubator	Graffe	* window broken * lock broken

Check within ☐ Week ☒ ASAP

Engineer Comments

window and Lock were broken. They
have been fixed.

End Comments

Ferre

Requested by

Ahmad Alawadhi

Checked by

Ferre

Approved by



FIELD SERVICE REPORT

LCS 12910

CUSTOMER ALORF Hospital	EQUIPMENT Incubator	MODEL NO. Givatte
JOB NO.	LOCATION NICU	SERIAL NO. HDHT 50690

DATE
16 / 01 / 2025

ASSET

CONTRACT

COST CENTER
4502

BILL PARTS / LABOR ☒

WARRANTY ☐

CONTRACT ☐

INSTALLATION ☐

OTHERS ☒

ENGINEER
Ahmed

HOURS
1

PARTS USED			
QTY.	PART NUMBER	SIV	DESCRIPTION

PROBLEM, DIAGNOSIS AND ACTION

⊕ service call attended

⊕ Unit checked

⊕ Problem: window and lock are broken.
They have been fixed and they are
in good condition

⊕ Repair Request needed for Labor

REMARKS

JOB COMPLETED ☒ Yes ☐ No

AWAITING PARTS ☐ Yes ☒ No

ATC ENGINEER SIGNATURE

USER SIGNATURE
Fene Joy Williamson

AUTHORIZED SIGNATURE & STAMP