The Inspector's Eye

Automated Structural Analysis Report

Total Infrastructure Nodes Analyzed: 18

Total Structural Defects Detected: 27

Immediate Action Required (Critical Faults): 22

Node Analysis: Volker_DSC01648_1112_284_1394_1323_jpg.rf.e74491ce2c72b608245

Defect ID	Severity	Span Ratio (%)	AI Confidence (%)
1	CRITICAL	73.98	37.01

Node Analysis: cracktree200_6303_jpg.rf.cbd7082697d58f0a7f785e06b7251a48.jpg



Defect ID	Severity	Span Ratio (%)	AI Confidence (%)
1	CRITICAL	46.06	66.29
2	CRITICAL	46.54	47.56
3	CRITICAL	56.71	36.43

Node Analysis: Rissbilder_for_Florian_9S6A2844_34_2177_3257_2596_jpg.rf.cde3d6



Defect ID	Severity	Span Ratio (%)	AI Confidence (%)
1	CRITICAL	55.83	58.42
2	CRITICAL	55.11	54.29
3	CRITICAL	43.51	53.83
4	CRITICAL	70.38	47.91
5	MAJOR	28.02	44.51
6	MAJOR	34.13	33.48

Node Analysis: noncrack_noncrack_concrete_wall_12_3-jpg_jpg.rf.0f53ccf52c571fb3

STATUS: NO STRUCTURAL DEFECTS DETECTED.

Node Analysis: Rissbilder_for_Florian_9S6A2917_599_2662_2081_2529_jpg.rf.a305a5

STATUS: NO STRUCTURAL DEFECTS DETECTED.

Node Analysis: noncrack_noncrack_concrete_wall_89_7-jpg_jpg.rf.a035eff908a1b120

STATUS: NO STRUCTURAL DEFECTS DETECTED.

Node Analysis: GAPS384_train_0541_1_641_jpg.rf.d9a1406ad131d42df91eedfe3d1cel



Defect ID	Severity	Span Ratio (%)	AI Confidence (%)
1	MAJOR	28.44	46.84
2	MAJOR	33.9	32.05

Node Analysis: CRACK500_20160329_103609_1_721_jpg.rf.641316e231c17fd365b42a

Defect ID	Severity	Span Ratio (%)	AI Confidence (%)
1	CRITICAL	80.14	51.47

Node Analysis: CRACK500_20160316_144230_641_1081_jpg.rf.3c56840dccc215f360f3

STATUS: NO STRUCTURAL DEFECTS DETECTED.

Node Analysis: noncrack_noncrack_concrete_wall_54_60-jpg_jpg.rf.54b4d76bb09555

STATUS: NO STRUCTURAL DEFECTS DETECTED.

Node Analysis: Rissbilder_for_Florian_9S6A3087_226_1917_3517_3304_jpg.rf.7da1e0



Defect ID	Severity	Span Ratio (%)	AI Confidence (%)
1	CRITICAL	73.24	64.96
2	CRITICAL	72.85	62.16
3	CRITICAL	84.05	27.17

Node Analysis: Volker_DSC01630_735_214_1603_1563_jpg.rf.b046600d4ef6e84a8fad4



Defect ID	Severity	Span Ratio (%)	AI Confidence (%)
1	CRITICAL	75.84	56.98
2	CRITICAL	83.4	37.63

Node Analysis: noncrack_noncrack_concrete_wall_24_22-jpg_jpg.rf.3b3dd2f88d6e22

STATUS: NO STRUCTURAL DEFECTS DETECTED.

Node Analysis: CRACK500_20160307_145113_1_721_jpg.rf.4cb3281eec7e5fc58f734c5



Defect ID	Severity	Span Ratio (%)	AI Confidence (%)
1	CRITICAL	60.86	49.4
2	CRITICAL	83.06	27.23

Node Analysis: Volker_DSC01669_0_0_1824_2736_jpg.rf.862ce3d72fdf24f964b0e3cba



Defect ID	Severity	Span Ratio (%)	AI Confidence (%)
1	CRITICAL	69.6	55.29
2	CRITICAL	70.13	51.08

Node Analysis: CRACK500_20160328_153629_1_361_jpg.rf.1ac2bca5b9f4a63ac6d0c7



Defect ID	Severity	Span Ratio (%)	AI Confidence (%)
1	CRITICAL	68.34	56.82
2	CRITICAL	69.23	56.7

Node Analysis: noncrack_noncrack_concrete_wall_25_5-jpg_jpg.rf.c9a958c80f3a79b

STATUS: NO STRUCTURAL DEFECTS DETECTED.

Node Analysis: Volker_DSC01644_612_414_1320_1175_jpg.rf.8b8b5c7be1f515cd7e3a



Defect ID	Severity	Span Ratio (%)	AI Confidence (%)
1	CRITICAL	71.64	54.08
2	MAJOR	32.29	31.25
3	CRITICAL	65.17	26.71