



Overview: Part of spill impact on Ubie Well4S flowline right of way at Ubie. Picture taken during Joint Investigation of 7th July, 2011



Close-up: Cut section on Ubie Well4S flowline at Ubie. Picture taken during Joint Investigation of 7th July, 2011