



Overview: Part of spill impact on 24" Nkpoku-Bomu pipeline right of way at Egballor. Picture was taken during Joint Investigation of 9<sup>th</sup> March 2012.



Close up: Hacksaw cut on 24" Nkpoku-Bomu pipeline at Egballor. Picture was taken during Joint Investigation of 10<sup>th</sup> March 2012.