



Overview: Part of spill impact on 16" Egbema -Assa Pipeline route at Ekpeagha . Picture taken during Joint Investigation of 27-28th August, 2011



Close-up: Spill due to illegal fitting on 16" Egbema -Assa Pipeline at Ekpeagha . Picture taken during Joint Investigation of 27-28th August, 2011