



Overview: Part of spill impact on 8" Isimiri pipeline right of way at Obiakpu. Picture was taken during Joint Investigation of 21<sup>st</sup> March, 2012.



Close-up: Illegal fitting on 8" Isimiri pipeline at Obiakpu. Picture was taken during Joint Investigation of 20<sup>th</sup> March, 2012.