



Overview: Part of spill impact on 10" Ogini-Eriemu delivery line right of way at Ovrode. Picture was taken during Joint Investigation of 17th November, 2011.



Close-up: Illegal fitting on 10" Ogini-Eriemu delivery line at Ovrode. Picture was taken during Joint Investigation of 17th November, 2011.