



Overview: Extent of the spill incident impact at Rumuekpe flow station route in Rumuekpe . Picture was taken during JIV of 21st April, 2011



Close-up: saver-pit over flow due to blocked drainage at Rumuekpe flow station route in Rumuekpe. . Picture was taken during JIV of 21st April, 2011