



Overview: Extent of the spill incident impact on 12" Benisede - Isampou Pipeline route at Ekeremor. Picture was taken during JIV of 19 January 2011



Close-up: Leak from a hole on 12" Benisede - Isampou Pipeline at Ekeremor. Picture was taken during JIV of 19 January 2011