



Overview: Part of spill impact on Agbada 2 Well 41, 42 and 43 flowline at Umuohia.  
Picture was taken during Joint Investigation of 17th Sept. 2012.



Close-up: Missing flowlines from Agbada 2 Well 41, 42 and 43 flowlines at Umuohia. Picture was taken during Joint Investigation of 17th Sept. 2012.