



Overview: Part of spill impact on 6" Cawthorne - Channel Well 45T Flowline at Mbikiri.
Picture was taken during Joint Investigation of 28th October 2013.



Close-up: Indent at 7 o'clock position on 6" Cawthorne - Channel Well 45T Flowline at Mbikiri. Picture was taken during Joint Investigation of 28th October 2013.