



Overview: Part of the spill impact on Imo River Well59T flowline Right of Way at Igiriukwu. Picture taken during Joint Investigation of 15th June, 2011



Overview: Spill point area after repair on Imo River Well59T flowline Right of Way at Igiriukwu. Picture taken during Joint Investigation of 15th June, 2011