





Overview: Part of spill impact on 24" Npoku-Bomu trunkline right of way at Botem.
Picture was taken during Joint Investigation of 26th June 2012.



Close up: Hacksaw cut at 7 o'clock on Oweh Well8L/11L flowline at Otor-Oweh.
Picture was taken during Joint Investigation of 26th June 2012.



Close up: Hacksaw cut at 3 o'clock on Oweh Well8L/11L flowline at Otor-Oweh.
Picture was taken during Joint Investigation of 26th June 2012.