



Overview: Part of spill impact on 12" Imo River – Ogale pipeline at Owaza.
Picture was taken during Joint Investigation of 17th April 2012.



Close up: Illegal fitting on 12" Imo River – Ogale pipeline at Owaza.
Picture was taken during Joint Investigation of 17th April 2012.