



Overview: Part of spill impact at 16" Utorogu-Ughelli pumping station right of way at Iwhrekan. Picture was taken during Joint Investigation of 2nd November, 2011.



Close-up: Spill point at 16" Utorogu-Ughelli pumping station at Iwhrekan. Picture was taken during Joint Investigation of 2nd November, 2011.