



Close-up: Spill due to hacksaw cut on Akaso Well 10L flowline at Cawthorne Channel.
Picture taken during Joint Investigation of 16th August, 2011.