



Overview: Part of spill impact on 6" Obigbo North – New Elenwo pipeline right of way at Umusonya. Picture was taken during Joint Investigation of 18th December 2012.



Close up: Illegal fitting on 6" Obigbo North – New Elenwo pipeline at Umusonya. Picture was taken during Joint Investigation of 19th December 2012.