

<u>Close-up:</u> Cut section on Akaso Well3S flowline at Ilomatoru. Picture was taken during Joint Investigation of 15th December, 2011.