



Close-up: Ruptured Bean Box on Nembe Well 20L Well Head in Nembe Creek. Picture was taken during JIV of 24th May, 2011