



Overview: Part of spill impact on 4" Ubie Well4S flowline right of way at Idu Ekpeye.  
Picture was taken during Joint Investigation of 26<sup>th</sup> September 2013.



Close up: Hacksaw cut on 4" Ubie Well4S flowline at Idu Ekpeye. Picture was taken during Joint Investigation of 26<sup>th</sup> September 2013.