



Overview: Part of spill impact on Nkali Well 10L flow line Right of Way. Picture was taken during Joint Investigation of 1<sup>st</sup> September 2012.



Close-up: Illegal fitting on Nkali Well 10L flow line Right of Way . Picture was taken during Joint Investigation of 1<sup>st</sup> September 2012.