



Overview: Part of spill impact on Otamiri Well 5L/S Flowline at Umuechem.
Picture was taken during Joint Investigation of 8th Dec. 2012.



Close-up: Hacksaw cut on Otamiri Well 5L/S Flowline at Umuechem. Picture was taken during
Joint Investigation of 8th Dec. 2012.