



Overview: Part of spill impact on 20" Buguma-Alakiri Trunkline at Daily Bread (Bukuma).
Picture was taken during Joint Investigation of 23rd Sept. 2012.



Close-up: Illegal fitting on 20" Buguma-Alakiri Trunkline at Daily Bread (Bukuma). Picture was taken during
Joint Investigation of 23rd Sept. 2012.