



Close-up: Evidence of mechanical grinding on the surface of the 24" Alakiri-Bonny Pipeline in Creek6. Picture was taken during JIV of 7th May 2011



Close-up: Evidence of grinding and drilled hole on 24" Alakiri-Bonny Pipeline at Kalibiama. Picture was taken during JIV of 8th May 2011