



Overview: Part of spill impact on 4" Nun River Well13T flowline right of way at Oporoma. Picture was taken during Joint Investigation of 4th September 2013.



Close up: Hacksaw cut on 4" Nun River Well13T flowline at Oporoma. Picture was taken during Joint Investigation of 4th September 2013.