



Overview: Part of spill impact Cawthorne Channel 2 Well 28T at Owame-Ama Okpoama.  
Picture was taken during Joint Investigation of 28<sup>th</sup> Nov. 2012.



Close-up: Failed Clamp on Cawthorne Channel 2 Well 28T at Owame-Ama Okpoama.  
Picture was taken during Joint Investigation of 28<sup>th</sup> Nov. 2012.