



Overview: Part of spill impact on on 18" Assa-Rumuekpe pipeline right of way at Awara. Picture was taken during Joint Investigation of 24<sup>th</sup> February 2012.



Close-up: Failed clamps on 18" Assa-Rumuekpe pipeline at Awara. Picture was taken during Joint Investigation of 25<sup>th</sup> February 2012.