



Close up: Illegal fitting on Imo River1 Well57L flowline at Igiriukwu. Picture was taken during Joint Investigation of 9th August 2012.