



Overview: Part of spill impact on 8" Obigbo North – Elenwa pipeline right of way at Umusia. Picture was taken during Joint Investigation of 2nd November 2012.



Close up: Illegal fitting on 8" Obigbo North – Elenwa pipeline at Umusia. Picture was taken during Joint Investigation of 3rd November 2012.