



Overview: Part of spill impact on 8" Umuechem-Nkpoku pipeline right of way at Umuesele. Picture was taken during Joint Investigation of 9th August 2012.



Close up: Illegal fittings on 8" Umuechem-Nkpoku pipeline at Umuesele. Picture was taken during Joint Investigation of 9th August 2012.



Closeup: Illegal fittings on 8" Umuechem-Nkpoku pipeline at Umuesele. Picture was taken during Joint Investigation of 9th August 2012.