



Overview: Part of spill impact on 12" Imo River1 pipeline right of way at Uzuaku.
Picture was taken during Joint Investigation of 19th May 2012.



Close up: Illegal fittings on 12" Imo River1 pipeline at Uzuaku. Picture was taken
during Joint Investigation of 19th May 2012.