

<u>Close-up:</u> Spill due to hacksaw cut on 14" Okordia-Rumuekpe pipeline at Ikarama.
Picture taken during Joint Investigation of 12<sup>th</sup> August, 2011.

1