



Overview: Extent of the spill incident impact at 28" Trans Forcados Pipeline route in Chanomi.
Picture was taken during JIV of 10 March 2011



Close-up: Illegally welded point on 28" Trans Forcados Pipeline route in Chanomi. Picture
was taken during JIV of 10 March 2011