



Overview: Part of spill impact on 24" Npoku-Bomu Trans Niger Pipeline right of way at Nonwa. Picture was taken during Joint Investigation of 20<sup>th</sup> June 2012.



Close up: Illegal fittings on 24" Npoku-Bomu Trans Niger Pipeline at Nonwa. Picture was taken during Joint Investigation of 20<sup>th</sup> June 2012.