



Close up: Illegal fitting on 12" Imo River2 – Ogale pipeline at Owaza. Picture was taken during Joint Investigation of 18<sup>th</sup> July 2012.