



Overview: Extent of the spill incident impact on 12" Imo River Pipeline at Owaza. Picture was taken during JIV of 12<sup>th</sup> May, 2011



Overview: Illegally welded point on 12" Imo River Pipeline at Owaza. Picture was taken during JIV of 12<sup>th</sup> May, 2011