



Overview: Part of spill impact on 10" Santa Barbara pipeline right of way at Santa Barbara. Picture was taken during Joint Investigation of 7<sup>th</sup> February 2013.



Close up: Illegal fitting on 10" Santa Barbara pipeline at Santa Barbara. Picture was taken during Joint Investigation of 8<sup>th</sup> February 2013.