



Overview: Part of spill impact on 36" Nkpoku-Bomu pipeline right of way at Eneka. Picture was taken during Joint Investigation of 25th July 2012.



Close up: Multiple illegal fittings on 36" Nkpoku-Bomu pipeline at Eneka. Picture was taken during Joint Investigation of 25th July 2012.