



Close up: Illegal coffer dam on 28" Trans Forcados pipeline at Oteghele. Picture was taken during Joint Investigation of 20th October 2012.



Close up: Illegal fitting on 28" Trans Forcados pipeline at Oteghele. Picture was taken during Joint Investigation of 20th October 2012.